



DATE:

August 27, 2003

TO:

King County International Airport Tenants

distributed by e-mail and fax

FROM: \\ Robert I. Burke, AAE, Airport Director

SUBJECT: \*KWY 13R/31L Partial Closure -August 28, 2003 (Thursday)

KCIA/Boeing Field will be performing routine pavement maintenance on Runway 13R/31L over the next 6 weeks. This will be preventative maintenance primarily involving crack sealing and minor patching to ensure pavement integrity over its useful life.

Additionally, the Airport will begin a major electrical rehabilitation of Taxiway Alpha throughout the month of September. This will involve replacing the electrical cable and transformers; therefore, extensive work will be required on the taxiway and in the taxiway safety areas. For both projects, please check NOTAMs daily.

The start of the runway pavement maintenance work has been scheduled for August 28, 2003 (Thursday) from 11:00 - 14:00 (local time). The first 2000 feet of Runway 31L will be closed and will have a relocated threshold. Additionally, taxiway intersections A10, A11, B7 and B10 will be closed. The PAPI and REILs for Runway 31L will be out of service during this time.

Therefore, if 13R is active (south flow), there will be 8001 feet available for arrival and departure. If 31L is active (north flow), there will be 8001 feet available for departure and arrival.

Please check NOTAMs daily for changes.

**2**001 08/27/2003 18:08 FAX 206 296 0190 KING COUNTY INTL AIRPORT \*\*\*\*\*\*\*\*\*\* MULTI TX/RX REPORT \*\*\*\*\*\*\*\*\*\* 0274 TX/RX NO 1 PGS. TX/RX INCOMPLETE \_\_\_\_ TRANSACTION OK SEATTLEJETSVC [\*001]9p7677931 **AEROFLIGHT** [\*002]9p7647102 AIR TRANSPORT [\*003]9p7621223 Airborne Express [\*004]9p7630381 Airlift NW [\*005]9p5211865 AIRPAC AIRLINES [\*006]9p7626357 AMERICAN AVIONIC [\*007]9p7632036 AMERIFLIGHT [\*008]9p7636239 AVIATION PARTNER [\*009]9p7621158 AVIATOR STORE [\*010]9p7633428 AVIATION TRNG [\*011]9p7647112 BAX GLOBAL [\*012]9p7620611 BOEING CO [\*013]9p6555116 CALIBER INSPECT [\*014]9p7648124 CLASSIC HELICOPT [\*015]9p7674018 GALVIN FLYING [\*016]9p7679333 HELIJET [\*018]9p7689458 KC JETCENTER [\*019]9p7641904 KTC AVIATION [\*020]9p7680483 LINDEAN AIRCRAFT [\*021]9p7626046 NAT'L AVIATION [\*022]9p7641312 NORDSTROM [\*023]9p7681715 PISTOL CREEK [\*024]9p7634837 SEA JET STREAM [\*025]9p7623542 SERVICE GRP [\*026]9p7633320 SOUND AERIAL SVY [\*027]9p7630381 TAG AVIATION [\*028]9p7641986 UPS [\*029]9p7674920 US CUSTOMS

[\*030]9p5536851

[\*031]9p5530190 [\*032]9p7643862

[\*033]9p7644760

[\*034]9p7671550

[\*035]9p76B1947

[\*036]9p7674539

[\*037]9p7679464

[\*038]9p7645707

[\*039]9p7635156

[\*040]9p7622997

[\*041]9p7677662

[\*042]9p7633964

[\*043]9p7621561

[\*044]9p7637761

[\*045]9p7625732

[\*046]9p7674047

[\*047]9p7625481

[\*048]9p7640142

[\*048]9p7675604

[\*050]9p7671726

[\*051]9p7094323

[\*052]54056

KCSlip4 34370

US IMMIGRATIONS

WA AIR NAT'L GRD

VALKERIE CORP WA AUDIOLOGY

NW SEAPLANES

WINGSALOFT

WESTERN METALS

MUS OF FLIGHT

S SEATTLE CC

**DUNCAN AVIONICS** 

GALVIN-MAIT BLD

MENTE AVIATION

OTTER CORP/JEM

KGF AVIATION

AIRTECH

MJL AIRPARTNERS

INTELL VENTURES

CASCADE FLIGHT

RAINIER AVIATION

OLDTHYMEAVIATION

**EMERGENCY MGMNT** 

EXEC FLIGHT

[ \*3]60514 SAFETY & CLAIMS
[\*\054]64271 SPEC\_OPS/GUARD
[\*\055]8p6142381807p3947395 AIRNET
[\*\056]8p6042734644p3947395 HELIJETFLITEOPS
ERROR INFORMATION
[\*\017]9p7689700 GUIDO PERLA





DATE:

August 27, 2003

TO:

King County International Airport Tenants

distributed by e-mail and fax

FROM Robert I. Burke, AAE, Airport Director

SUBJECT: ~ KWY 13R/31L Partial Closure -August 28, 2003 (Thursday)

KCIA/Boeing Field will be performing routine pavement maintenance on Runway 13R/31L over the next 6 weeks. This will be preventative maintenance primarily involving crack sealing and minor patching to ensure pavement integrity over its useful life.

Additionally, the Airport will begin a major electrical rehabilitation of Taxiway Alpha throughout the month of September. This will involve replacing the electrical cable and transformers; therefore, extensive work will be required on the taxiway and in the taxiway safety areas. For both projects, please check NOTAMs daily.

The start of the runway pavement maintenance work has been scheduled for August 28, 2003 (Thursday) from 11:00 - 14:00 (local time). The first 2000 feet of Runway 31L will be closed and will have a relocated threshold. Additionally, taxiway intersections A10, A11, B7 and B10 will be closed. The PAPI and REILs for Runway 31L will be out of service during this time.

Therefore, if 13R is active (south flow), there will be 8001 feet available for arrival and departure. If 31L is active (north flow), there will be 8001 feet available for departure and arrival.

Please check NOTAMs doily for changes

TRANSMISSION OK

TX/RX NO
RECIPIENT ADDRESS
DESTINATION ID
ST. TIME

ST. TIME
TIME USE
PAGES SENT
RESULT

0279 97689700

08/28 08:31 01'08 1

٥ĸ





DATE:

August 27, 2003

TO:

King County International Airport Tenants

distributed by e-mail and fax

FROM: Robert I. Burke, AAE, Airport Director

SUBJECT:

RWY 13R/31L Partial Closure -August 28, 2003 (Thursday)

KCIA/Boeing Field will be performing routine pavement maintenance on Runway 13R/31L over the next 6 weeks. This will be preventative maintenance primarily involving crack sealing and minor patching to ensure pavement integrity over its useful life.

Additionally, the Airport will begin a major electrical rehabilitation of Taxiway Alpha throughout the month of September. This will involve replacing the electrical cable and transformers; therefore, extensive work will be required on the taxiway and in the taxiway safety areas. For both projects, please check NOTAMs daily.

The start of the runway pavement maintenance work has been scheduled for August 28, 2003 (Thursday) from 11:00 - 14:00 (local time). The first 2000 feet of Runway 31L will be closed and will have a relocated threshold. Additionally, taxiway intersections A10, A11, B7 and B10 will be closed. The PAPI and REILs for Runway 31L will be out of service during this time.